

SAFETY ALERT

SERVICE BULLETIN

SERVICE LETTER

MANDATORY

Date of Notice: 27 JULY 2019

Effective Date: 27 JULY 2019

Deadline: According ROTAX SB-912-073 last Issue

Subject: Replacement of circlip (carburetor) for ROTAX® Engine Type 912 and 914 (Series)

Superseded Notice: According ROTAX SB-912-073 last Issue

Compliance: According ROTAX SB-912-073 last Issue

Affected Aircraft:

Make: Texas Aircraft Manufacturing, LLC

Model: Colt 100

Affected Serial Numbers: TXA001

References: ROTAX SB-912-073 / SB-914-055 last Issue. Please refer to www.flyrotax.com and www.rotax-owner.com.

Discussion: According ROTAX SB-912-073 last Issue

Authorized to Perform: A&P and According ROTAX SB-912-073 last Issue

Labor time: Estimate 1.5 hours

Material Required: According ROTAX SB-912-073 last Issue

Corrective Action/Instruction: According ROTAX SB-912-073 last Issue

Page: 1 of 1

SAFETY ALERT: for Notices that require action to correct an unsafe condition that is likely to occur in other aircraft of the same model.

SERVICE BULLETIN: for Notices of actions considered necessary by the manufacturer to prevent an unsafe condition from developing in the fleet.

SERVICE LETTER: for Notices that do not necessarily recommend future action but are primarily for promulgation of COS information.