

SAFETY ALERT

SERVICE BULLETIN

SERVICE LETTER

MANDATORY

Date of Notice: 27 JULY 2019
Effective Date: 27 JULY 2019
Deadline: According ROTAX SB-912-073 last Issue
Subject: Replacement of circlip (carburetor) for ROTAX® Engine Type 912 and 914 (Series)
Superseded Notice: According ROTAX SB-912-073 last Issue
Compliance: According ROTAX SB-912-073 last Issue
Affected Aircraft:
Make: Texas Aircraft Manufacturing, LLC
Model: Colt 100
Affected Serial Numbers: From TXA001 to TXA006
References: ROTAX SB-912-073 / SB-914-055 last Issue. Please refer to www.flyrotax.com and www.rotax-owner.com.
Discussion: According ROTAX SB-912-073 last Issue
Authorized to Perform: A&P and According ROTAX SB-912-073 last Issue
Labor time: Estimate 1.5 hours
Material Required: According ROTAX SB-912-073 last Issue
Corrective Action/Instruction: According ROTAX SB-912-073 last Issue
Page: 1 of 1

SAFETY ALERT: for Notices that require action to correct an unsafe condition that is likely to occur in other aircraft of the same model.
SERVICE BULLETIN: for Notices of actions considered necessary by the manufacturer to prevent an unsafe condition from developing in the fleet.
SERVICE LETTER: for Notices that do not necessarily recommend future action but are primarily for promulgation of COS information.